

AIRPORT

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY High, Medium Low	COMPLIANT AREAS	COMMENTS
1. Parking	Parking Lot	Need another Handicapped Parking Spot - 90 Parking Spots - 3 Handicapped - (4 Handicapped Spots Required) The parking lot surface and side walk, slightly uneven	High	Handicapped	
2. Path of Travel	Front	No Handrails - Not due to slope or height of ramp, due to length of ramp	Low	Front - All ramps - Appropriate Slope	The sidewalk was not completely smooth
3. Entrance & Doors	Back	No Handrails - Due to length, slope, and height	High	Back - All Ramps - Appropriate Slope	
	Front Door	Threshold - .28 (.25 minimum)	Low	Automatic Doors - Easy to Open	
	Restaurant Door	Door Width - 32 inches except at bar on door (32 inch minimum)	Low	Elevator Car Size: Door Width, Length (off by 1 inch)	NO BRAILLE
4. Elevators, Stairs & Railings	Elevators	Lack of raised characters and braille for controls on the inside and outside	High	Height of Controls - Internal and External	
		Audible Sounds (once for up direction, twice for the down direction)	High	Handrails present, appropriate height - Internal & external	No handrails on landing
	Stairs - Internal	Handrails do not extend one foot beyond either top or bottom riser	Medium	Stair run length - internal	
		Stair riser height - 8 1/2 inch (7 inch maximum)	Low		

	Stairs - External	Handrails do extend at the bottom riser by a foot, but not the top riser	Medium	Stair rise and run measurements	
5. Common Areas (Interior and	Service Counter	Height of Service counter - 38 Inches (36 inch minimum)	Low		
	Fixed Tables - Restaurant			36 Inches accessible walk space between tables	
	Fixed Tables - Lobby	Knee Clearance - 24 inches (27 inch maximum)	Medium	Chairs had wheel, so the chairs were easily moveable	
6. Public Restrooms and Drinking Fountains		No Braille on Accessibility Signage			
	Men's Restroom	Soap Dispenser - 54 inches high (48 high max)	High	Door Width, Side Bars	
		Toilet seat too low - 16 1/2 inches (17 inch in minimum)	Low	Traditional Stall Measurements not used - Alternate stall used 42 inches x over 5 feet - (36 inches x 66 inches required)	
		No Braille on Accessibility Signage			
	Women's Restroom	Paper Towel Dispenser - 56 1/2 inches high (48 high max) Toilet seat too low - 16 1/2 inches (17 inch in minimum)	High Low		

ANIMAL CONTROL

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY	AMOUNT	COMPLIANT AREAS	COMMENTS
1. Parking	Parking Lot	No Handicapped Parking Sign - The Parking Spot is Van Accessible qualified, sign should read "Van Accessible"	Medium		Dedicated Handicapped Parking - 11 Parkings Spot - 1 Designated Parking Spot	Fading Lines - Need to be replaced eventually
11 Parking Spots/ 1 Handicapped		No Access Aisle	High			
2. Path of Travel	Exterior	NO RAMPS			The accessible parking on the shortest route to the entrance Surface was not steeper than 1:48 Front Door Width	
3. Entrance & Doors	Exterior	Signs pointing to the Back Entrance - For Animal Pick Up	Low			
	Interior	Heavy Doors - Change Doors? Cannot leave the doors propped open in this bathroom	Medium/High			
5. Common Areas (Interior and Exterior)	Interior	Height of Service Counter - 42 inches, 6 inches too high	Low		Depth of the Counter	
		Toe Clearance height - 4 inches high - 9 inches required	Low		Toe Clearance Width	
		Toe Clearance depth - 3 inches deep - 17 inches required	Low			
6. Public Restrooms and Drinking Fountains		Restroom Door - 30 inches wide (32 inch min)	Medium/High		Sink Height, Side Bar in Stall	

		Soap Dispenser - 52 1/2 inches high (48 high max)	High	
--	--	---	------	--

CHILD CARE CENTER

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY High, Medium Low
1. Parking			
2. Path of Travel	Outdoor Ramps	Both ramps in the front are over 6 feet, and neither ramps had handrails	Medium /High
3. Entrance & Doors	First Front Door	Threshold - .77 which <1/4 maximum - Place a Mat to decrease the change in level	High
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)	Service Counter	Height - 42 inches/ 6 inches too high	Low
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements	Playground - Front	No transfer system (Old playground) One transfer system, not near entrance, there is fibar, but you have to through a deep dip in the concrete	
8. Notes:	Playground- Left		

CITY HALL

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY (High, Medium, Low)	AMOUNT (Approximate or TBD)	COMPLIANT AREAS	THINGS TO WATCH
1. Parking	Handicapped Spots	There are no handicapped van designated spots	Low		Adequate Number of Handicapped Spots	Consider placing another Handicapped space whenever the spaces are re-lined
	Ramps (5)	Ramp (located) - is not compliant. The slope is too steep, and based on the rise and run, the slope needs handrails, but not to the degree that its prohibited	Medium/ High		4 out of the 5 ramps are compliant	
3. Entrance & Doors						Doors to the office must continue to stay propped open for access into the office, including the doors in the council chambers and meeting halls.
4. Elevators, Stairs & Railings	Elevator	Elevator Car Width - 74 inches - 8 inches too small	low/medium			May qualify for the Elevator Exemption
	Entrance	Handrails height- 32 inches - 2 inches too low	low			

5. Common Areas (Interior and Exterior)	All Staircases Council Chambers	Lacked the minimum requirement of having 12 inches of the handrail extended at the top and the bottom				Create a handicapped space, at least one with signage
	Counters (8)				All of the counters were compliant based on their height	
6. Public Restrooms and Drinking Fountains	All Restrooms (4)	Each handicapped stalls is at least 6 inches to small in each bathroom				
	Men First Floor	Toilet Seat- one inch to low - add an extra layer for the seat	Low			
	Women's First Floor	Soap Dispenser - 50 inches to high- Lower the soap dispenser 2 inches	High			

COLUMBUS LEARNING CENTER

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)
1. Parking		
2. Path of Travel		
3. Entrance & Doors	Door Threshold	The first door threshold was beveled - Mat needs to add in between the doors, to reduce the change in level
4. Elevators, Stairs & Railings	Elevators	The controls are not marked with braille
	Ramp/Elevators	Ramp is not compliant, but there are elevators are available. HOWEVER, there needs to signage directing traffic to elevator before they get to the non-compliant ramp
	Back Elevators	No sign directing handicapped individuals to the elevators
5. Common Areas (Interior and Exterior)	Auditorium	Single or double wheelchair space - It is provided but no signage

HIGH			
MED			
LOW			

PRIORITY	AMOUNT (Approximate or TBP)	COMPLIANT AREAS	THINGS TO WATCH
High / Medium Low			
		Size of the elevator	
HIGH			
HIGH			
HIGH			

COMMONS

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)
2. Path of Travel		
3. Entrance & Doors	Front Doors	The series of doors that are adjacent- 43 1/2 inches in between the series of the door - the minimum is 48 inches
4. Elevators, Stairs & Railings	Elevators	External controls did not have braille
5. Common Areas (Interior and Exterior)	Service Desk - Office	Height - 43 inches - 7 inches too high
6. Public Restrooms and Drinking Fountains		
7. Special Rooms, Spaces, and Elements		
8. Notes:		

PRIORITY	AMOUNT (Approximate or TBD)	COMPLIANT AREAS	THINGS TO WATCH
High, Medium Low			
Medium			
Medium			
Medium			

EASTSIDE COMMUNITY CENTER

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)
1. Parking	Back Parking Lot	No lines
2. Path of Travel	Front Parking Lot	The lines are beginning to fade
3. Entrance & Doors	Back Ramp	No Handrails; based on the distance
4. Elevators, Stairs & Railings		
5. Common Areas (Interior and Exterior)		
6. Public Restrooms and Drinking Fountains	Bathroom	Soap Dispenser - 59 inches - 11 inches too high, move down
7. Special Rooms, Spaces, and Elements	Water Fountains	Water low one inch too short
8. Notes:		

FIRE STATION 1

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
1. Parking			High, Medium Low
2. Path of Travel			
3. Entrance & Doors	Front Door	Door threshold .33 - <.25	Low
4. Elevators, Stairs & Railings	Stairs	Two Floors - No elevator - Historic Building	Low
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains	Paper Towel Dispenser	54 inches - 6 inches too high - Lower the dispenser	High
7. Special Rooms, Spaces, and Elements			
8. Notes:			

FIRE STATION 2

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
1. Parking			High, Medium
2. Path of Travel			Low
3. Entrance & Doors			
4. Elevators, Stairs & Railings	Stairs	Two Stories - Not a Historic Building	Medium/ High
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains	Paper Towel Dispenser	53 inches high - 5 inches too high - Lower the dispenser	High
7. Special Rooms, Spaces, and Elements			
8. Notes:			

FIRE STATION 3

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
1. Parking	Parking Spots	There is no handicapped parking spots	Medium/ High
2. Path of Travel	Ramp	Slope 8.8% - 0.5% too high - historic building, low traffic location	Low
3. Entrance & Doors			
4. Elevators, Stairs & Railings	Stairs	Two Floors - No Elevator - Historic Building	Low
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains	Paper Towel Dispenser	51 inches - 3 inches to high - Move dispenser down	Medium
7. Special Rooms, Spaces, and Elements			
8. Notes:			

FIRE STATION 4

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
1. Parking	No Parking Lot		High
2. Path of Travel	No Accessible Path	If a parking lot is created, there can be a designated accessible path of travel	pending
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains	Stall	60 inches x 48 inches - 8 inches too small	Medium
		No Side bars	
	Soap Dispensers	50 inches too high - 2 inches to high	Low
	Toilet Seat	Toilet Seat - 15 inches- too short	Medium
7. Special Rooms, Spaces, and Elements			
8. Notes:			

FIRE STATION 5

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS <i>(Description, Calculations)</i>
1. Parking	Parking Spots	No Van Handicapped Parking Spots
2. Path of Travel	Parking Pathway	Uneven ground from parking spaces to sidewalk. 1/2 to 3/4 inch difference
3. Entrance & Doors		
4. Elevators, Stairs & Rallings	Stairs	Two Stories - No elevator
5. Common Areas (Interior and Exterior)		
6. Public Restrooms and Drinking Fountains		
7. Special Rooms, Spaces, and Elements		
8. Notes:		

FIRE STATION 6

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)
1. Parking	No Designated Parking Spots	
2. Path of Travel		
3. Entrance & Doors		
4. Elevators, Stairs & Railings		
5. Common Areas (Interior and Exterior)		
6. Public Restrooms and Drinking Fountains	Paper Towel Dispenser	50 inches - 2 inches too high - Move the dispenser down
	Soap Dispenser	49 inches - 1 inch too high - Move the dispenser down
7. Special Rooms, Spaces, and Elements		
8. Notes:		

PRIORITY	AMOUNT (Approximate or TBD)	COMPLIANT AREAS	THINGS TO WATCH
High, Medium Low			
Medium			
Medium			

GALEGE

GARAGE

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)
1. Parking	Parking Lot	Not enoughhandicapped parking spots The one handicapped parking spot was not the shortest route to the accessible entrance
2. Path of Travel	Buzzer System	Lines were fading Improve sign - Use the International Sign for Disability, and include braille
3. Entrance & Doors		The front desk is located on the second floor and there is no elevator. The City Garage has developed a system that works, because adding an elevator would be an undue burden, therefore, they need only to improve the signage to fully accommodate persons with disability to come into compliance
4. Elevators, Stairs & Rollings	Stairs	
5. Common Areas (Interior and Exterior)		
6. Public Restrooms and Drinking Fountains	Men's Restroom	Stall - 60 inches x 33 inches- 0 x 22 inches too short, because the stall doesn't meet the alternate stall requirements - small traffic area Soap dispensers - Height - 50 inches - 2 inches to high-Lower the dispenser
		Lower the dispenser
		Lower the dispenser
	Women's Restroom	Stall - 60 inches x 20 inches- 0 x 16 inches too short, because the stall doesn't meet the alternate stall requirements - small traffic area
	Water Fountain	Spout height - 38 inches - 2 inches too high
7. Special Rooms, Spaces, and Elements		
8. Notes:		

PRIORITY	AMOUNT (Approximate or TBD)	COMPLIANT AREAS	THINGS TO WATCH
High, Medium Low			
pending			
High			
High			
High			
High			
Low			

WILLIAMS CENTER

MILL RACE CENTER

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)
1. Parking		
2. Path of Travel		
3. Entrance & Doors		
4. Elevators, Stairs & Railings		
5. Common Areas (Interior and Exterior)	Service Counter	Height - 45 inches - 9 inches too high
6. Public Restrooms and Drinking Fountains		
7. Special Rooms, Spaces, and Elements		
8. Notes:		

POLICE

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)
1. Parking		
2. Path of Travel		
3. Entrance & Doors	Interviews (4)	All four interview rooms are too small. There needs to be one place/ interview room that is accessible. Pick an accessible place to interview persons in wheel chairs
4. Elevators, Stairs & Railings		
5. Common Areas (Interior and Exterior)		
6. Public Restrooms and Drinking Fountains	Water Fountain	The water fountain was broken, and the sprout - height 40 inches- 4 inches too high
7. Special Rooms, Spaces, and Elements		
8. Notes:		

PRIORITY	AMOUNT (Approximate or TDD)	COMPLIANT AREAS	THINGS TO WATCH
High, Medium Low			
Medium/ High			
Low			

1. If the amount of the...
 2. If the amount of the...
 3. If the amount of the...
 4. If the amount of the...
 5. If the amount of the...
 6. If the amount of the...
 7. If the amount of the...
 8. If the amount of the...
 9. If the amount of the...
 10. If the amount of the...

TRANSIT

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)
1. Parking	Parking Lot	No Van Handicapped Parking Spot, not required for the number of spaces
2. Path of Travel		
3. Entrance & Doors		
4. Elevators, Stairs & Railings		
5. Common Areas (Interior and Exterior)		
6. Public Restrooms and Drinking Fountains		
7. Special Rooms, Spaces, and Elements		
8. Notes:		

PRIORITY	AMOUNT (Approximate or TBD)	COMPLIANT AREAS	THINGS TO WATCH
High, Medium LOW			
Receive complaints about the door being heavy; High Traffic location			



[Faint, illegible text, likely bleed-through from the reverse side of the page. The text is mostly obscured by noise and low contrast.]

UTILITIES

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS <i>(Description, Calculations)</i>
1. Parking	Parking Lot	No Van Accessible Parking Signs and Van Accessible size spots
2. Path of Travel	Ramps (3)	The two side ramps have a caved in part causing the cross slope to be too high in two parts on the ramps at 4.5% & 5.7% on ramp 1 and 4.8% on ramp 2 The front ramp is compliant, but has varying slopes down it
3. Entrance & Doors	Door Threshold	the door threshold is not beveled, there is a piece of metal sticking up
4. Elevators, Stairs & Rollings		
5. Common Areas (Interior and Exterior)		
6. Public Restrooms and Drinking Fountains	Womens/Mens Restrooms Paper Towel Dispenser	Stall - Over 60 inches x 48 inches - 8 inches too small for standard stall, but fits the alternate stall size Height - 50 inches - 2 inches too high - Lower dispenser
7. Special Rooms, Spaces, and Elements		
8. Notes:		

VOLUNTEERS IN MEDICINE

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY High, Medium Low
1. Parking	Parking Lot	Lines were faded, couldn't even count all the spaces, some of the handicapped spots were painted - No signs	High
		Rocky surface, uneven, and bumpy	
2. Path of Travel		The handicapped spot on the end, the pathway to the door is blocked by bike racks if a person in a wheelchair was to use that path	
	Parking Lot to Door		
	Ramps (4)	All (4) Ramps were too high	
3. Entrance & Doors		The handrails were not between 34-38 inches	
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)	Service Counter	Height - 42 inches & 41 inches - 6 inches & 5 inches too high	Low
6. Public Restrooms and Drinking Fountains		Stall - 94 inches x 32 inches - 0 X 4 inches to small based on the alternate bathroom available, there has to be two side bars	Medium / High
	Men's Restrooms	No Back Bars	
	Women's Restrooms	Stall - 90 inches x 36 inches - 0 x 20 inches to small for standard stall, but the measurements meet the alternate, but there needs to be another side bar	Medium / High
	Paper Towel Dispenser	Height - 54 inches - 6 inches too high	
7. Special Rooms, Spaces, and Elements			
8. Notes:			