

BLACK WELL PARK

BLACK WELL PARK			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium Low
1. Parking		Missing Handicap signs	High
		Need Handicapped Parking Spots near Park	Low
2. Path of Travel		No Handrails on ramp - The rise is above 6 inches, and longer than 72 inches	Medium
5. Common Areas (Interior and Exterior)	Stands/ Rows of Seats by back Soccer Fields	1. There are no aisles	
		2. No accessible way to get to the only stands in the park	
		3. Handrails do not extend to the ground, must reach up for handles	
7. Special Rooms, Spaces, and Elements	Playground		
8. Notes:			

AMOUNT (Approximate or TBD)	COMPLIANT AREAS	COMMENTS
	# of handicapped spots in relation to other parking spots	
		There are parking spots next to the park but they belong to the school system, so if school is in session and someone wanted to go to the park, those spots may not be available for handicapped persons. And an out of town resident may not know that they are able to park behind the school on the property.
	Slope of Ramp	

CLIFTY CREEK

CLIFTY CREEK			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium Low
1. Parking	Dog Park	No designated handicapped parking spots at the Dog park	High
2. Path of Travel	Ramps - Restroom	Ramp- 23.5 long, Slope 12.5 %, should have been 8.33% - the Slope is non - compliant and there were no handrails	Medium
	Ramp	Ramp doesn't have handrails	Medium/ High
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)	Concession Stands	Height - 42 inches - 6 inches too high, stairs in front of the concession stand	
6. Public Restrooms and Drinking Fountains	Stall	40 inches x 49 inches - 16 inches too small x 11 inches too small	Medium
		There was no back bar, so the alternate measurements was not applicable to this stall	High
	Urinals	22 inches high - 5 inches higher than the minimum	Medium/ High
	Water Fountains	Water Flow- one inch too short; one inch too far from the edge	Low
7. Special Rooms, Spaces, and Elements	Playground	No smooth transition from the pathway to the fibar	

		The transfer system was too small, 18 inches from the ground	
8. Notes:			

DONNER CENTER AND PARK - Historic Building

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY High, Medium Low
1. Parking			
2. Path of Travel		Not a clear accessible pathway from the front of Donner Center to the Playground/Shelter area, there is a rocky path, then it turns into grass	
3. Entrance & Doors		No Accessible pathway from to the Basketball Court	
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains	Inside Pool Bathrooms Stall - Men/Women	42 inches x 60 inches - 6 inches too short	Low/ Medium
Inside Donner Center Bathrooms	Door	Door Width- 28 inches- 4 inches too short	Historic
	Stall	41 inches x Over 60 inches - 15 inches too small	Historic
7. Special Rooms, Spaces, and Elements			
8. Notes:			

g		
AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		
	Clear accessible pathway from Parking lot to Donner Center	

FOUNDATION FOR YOUTH

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium
			Low
1. Parking			
2. Path of Travel			
3. Entrance & Doors	Threshold	Threshold coming in is over 1/4 inch - place a mat to reduce the change in level between the ground and the threshold	Medium
4. Elevators, Stairs & Railings	Elevator	51 inches x 60 inches - too small	High
	Stairs inside	Door in between the stairs - keep the door open when possible	Low
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements			
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

GREENBELT GOLF COURSE

GREENBELT GOLF COURSE			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium, Low
1. Parking	Van Accessible	Have lanes large enough to be van accessible, need signs	Medium
	Signs	Trees covering some of the handicapped signs	Low
	Sidewalk	There are two handicapped areas - one area needs to be repaved and the sidewalk	Medium
2. Path of Travel			
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
	Men's and Women's Restroom	Stall - 60 inches x 41 inches - 0 x 15 inches to short	Medium/High
		Stall - No back bar	High
	Soap dispenser	Height- 51 inches - 3 inches too high - lower the dispenser	Medium/High
7. Special Rooms, Spaces, and Elements			
8. Notes:			

HARRISON RIDGE PARK

HARRISON RIDGE PARK			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium Low
1. Parking	Parking Lot	No Van Accessible Parking Spots	Low
2. Path of Travel	Ramps	Into Play ground areas - too steep	Medium/ High
		Tennis Courts - Too Steep	Medium/ High
3. Entrance & Doors	Tennis Courts	The door must be opened on the hill which would make it difficult if someone is in a wheel chair would make it difficult with a manual wheelchair	
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains	Water Fountain	The flow of water - did not reach the 4 inch maximum nor was the water flow within 5 inches of the edge - water pressure needs to be increased	
7. Special Rooms, Spaces, and Elements	Transfer Systems	Older Playground - Did not have a transfer system	
		No walkway to swings	
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

JACKSON STREET GARAGE

JACKSON STREET GARAGE			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium Low
1. Parking	Parking Spaces	There are handicapped spots distributed throughout all of the garage for purchasers and then there are handicapped parking spots for the public as well. There are less than 25 public parking spots	
2. Path of Travel			
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements			
8. Notes:			

AMOUNT (Approximate or TBD)	COMPLIANT AREAS	THINGS TO WATCH

LINCOLN PARK/ HAMILTON CENTER - Historic Build

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium Low
1. Parking	Front Parking Lot	Consider adding another handicapped parking spot	Low
	Adult Diamonds - Middle Lot	At least handicapped parking Spot that was less than 8 feet- need to be relined	High
2. Path of Travel	Hamilton Center	There is no ramp/sidewalk from the Hamilton to the rest of park	Medium/ High
	Adult Diamonds	The area between the sidewalks that are filled with gravel need to paved	Medium/ High
3. Entrance & Doors	Front Doors - Hamilton Center	Need accessibility signage on the two front doors that are inaccessible to prevent handicapped persons from going into the door that is not accessible.	HIGH
	General area	Larger signs on the door directing traffic to accessible bathrooms	High
4. Elevators, Stairs & Railings	Skating Rink Stands	Height- 9 inches - 2 inches too high	Medium
5. Common Areas (Interior and Exterior)	Service Counters	Height- 42 inches - 6 inches too high	Low
6. Public Restrooms and Drinking Fountains	Men's & Women's - Skating Rink	Stall - 39 inches x over 60 inches - 17 inches too short x 0	Medium
		No Mirror	
	Water Fountains	The flow of water is within 5 inches from the front of the unit	Low
7. Special Rooms, Spaces, and Elements	Basketball Court	No Pathway to basketball court	Medium/ High

8. Notes:			
------------------	--	--	--

--	--	--

McCULLOUGH'S RUN

McCULLOUGH'S RUN			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium Low
1. Parking			
2. Path of Travel			
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)	Tables	Table Height - 24 inches high x 19 inches wide - 4 inches to short (high) x 11 inches to short (wide) - No tables Handicapped accesible	Low/ Medium
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements	Transfer System	There was no transfer system on the playground	Low/ Medium
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

MEAD VILLAGE PARK

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium Low
1. Parking	Lot	No signs	Low
2. Path of Travel	Basketball Court	No sidewalk to basketball court or playground; there is only greass	Medium/ High
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements	Playground	There isn't an accessible route	Medium/ High
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH			
(Approximate or TBD)					

MILL RACE PARK

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY High Medium Low
1. Parking	Parking Lot	Need Van parking spaces signs - spaces are large enough	Low
	Parking Spots near River Shelter	Lines need to be relined	Medium
2. Path of Travel	From Parking Lot	Cracks in the sidewalk cause the pavement to be uneven, need to be repaved	
	Ramp	Two ramps - one by Park and the one on the amphitheater, both over 6 feet and they do not have handrails	Medium/ High
3. Entrance & Doors			
4. Elevators, Stairs & Railings	Elevator	Broken	
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains	Pond Restrooms	Stall - 54 inches x 54 inches - 6 inches x 2 inches too small	Medium
	Back Restrooms	Stall - Over 5 feet x 48 inches - 0 inches x 6 inches too small	Low
7. Special Rooms, Spaces, and Elements	Accessible Swings	There is not a clear path of travel to the accessible swings	Medium/ High
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

MORNINGSIDE PARK

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium, Low
1. Parking	Parking Lot	No designated parking; only street parking	
2. Path of Travel	Picnic Area	Uplifted ground (tree roots)- making the sidewalk uneven, greater than 1/4 inch - interrupting the path of travel	
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements			
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

NINTH STREET

NINTH STREET			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium Low
1. Parking	Street Parking	No Parking Lot - Street Parking - No Handicapped designated spots on the street	
2. Path of Travel	Ramp	The ramp and parts of the sidewalk are uneven. There is a higher than 1:48 between the path of travel and the border of the park. Needs to be level	Medium/ High
	Sidewalk	Uneven, bumpy	Medium/ High
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements	Transfer System	The Facility did not have a transfer System - But there is fibar surrounding the playgrounds - Access to the Playground needs to be improved - Look under Path of Travel	Low/ Medium
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

NOBLITT PARK

NOBLITT PARK			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High Medium Low
1. Parking	Parking Spaces	No handicapped Signs	Medium
		Lines were faded	Medium
		Parking lot needs to be repaved	Medium
2. Path of Travel			
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements			
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

OAKBROOK PARK

OAKBROOK PARK			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High / Medium
			Low
1. Parking	Parking Lot	Lines are faded	Medium
2. Path of Travel		No walkway from road/sidewalk to park , no walkway to th basketball court	Medium/ High
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements			
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		



PAR 3 GOLF COURSE

PAR 3 GOLF COURSE			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium
			Low
1. Parking	Parking Lot	No Van Accessible Parking Spots	Low
2. Path of Travel	Parking Lot	One path of travel, there are cracks in the sidewalk, and the sidewalk has raised, causing a change greater than 1:48.	Medium
3. Entrance & Doors	Door Threshold	Threshold - . 64 inches - too high	Medium/ High
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)	Service Counter	Height - 41 1/2 inches - 5 1/1 inches too high	Low
6. Public Restrooms and Drinking Fountains	Coat Hooks	Height - 65 inches - 13 inches too high - Provide at least one lower hook	Medium
7. Special Rooms, Spaces, and Elements			
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

PENCE STREET

PENCE STREET			
FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY High, Medium Low
1. Parking	Parking Lot	An access area is available but there are no lines, completely faded	Medium
		There was a drain in the access aisle, consider change the parking spot and the access aisle	Medium
2. Path of Travel	Parking Lot	No sidewalk from the parking lot to the park	Medium
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)	Basketball Court	No access to basketball court	Low
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements			
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		

SENIOR CENTER

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium, Low
1. Parking			
2. Path of Travel			
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains			
7. Special Rooms, Spaces, and Elements			
8. Notes:			

IN CONSTRUCTION

AMOUNT (Approximate or TBD)	COMPLIANT AREAS	THINGS TO WATCH



THE SERVICE CENTER - PARKS OPERATION

FACILITY AREA	SPECIFIC AREA	RECOMMENDATIONS (Description, Calculations)	PRIORITY
			High, Medium, Low
1. Parking			
2. Path of Travel			
3. Entrance & Doors			
4. Elevators, Stairs & Railings			
5. Common Areas (Interior and Exterior)			
6. Public Restrooms and Drinking Fountains	Restrooms	Coat Hooks - 64 inches - 18 inches too high- Have one lower coat hook	
7. Special Rooms, Spaces, and Elements			
8. Notes:			

AMOUNT	COMPLIANT AREAS	THINGS TO WATCH
(Approximate or TBD)		
[REDACTED]		

[REDACTED]